

## Plastic spare key for small MCP

---



**Part-No.: 704966**

With this plastic service key the housing is push opened to replace the glass pane and the test functionality of the manual call point is activated and reset.

**Common technical data**